



Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration
(Non-Mandatory Form)

IDENTITY <i>(As Used on Label and List)</i> ARDEX SD-F FEATHER FINISH – WHITE	Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.
--	---

Section I

Manufacturer's Name ARDEX ENGINEERED CEMENTS	Emergency Telephone Number (724) 857-6400
Address <i>(Number, Street, City, State and Zip Code)</i> 400 Ardex Park Drive Aliquippa, PA 15001 U.S.A.	Telephone Number for Information (724) 203-5000
	Date Prepared 10/01/2004
	Signature of Preparer <i>(Optional)</i>

Section II – Hazardous Ingredients/Identity Information

Hazardous Components <i>(Specific Chemical Identity: Common Name(s))</i>	OSHA PEL	ACGIH TLV	Other Limits Recommended	% <i>(optional)</i>
40% MAX PORTLAND CEMENT	65997-15-1	10MG/M ³	10MG/M ³	
45% MAX LIMESTONE	1317-65-3	N/A	30 MPPCF	
20% MAX VINYL ACETATE COPOLYMER	24937-78-8	10MG/M ³	10 MG/M ³	

Section III – Physical/Chemical Characteristics

Boiling Point	N/A	Specific Gravity (H ₂ O = 1)	1.2
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A
Solubility in Water	LESS THAN 50 G/1000 CM ³		
Appearance and Odor	FINE WHITE POWDER - ODORLESS		

Section IV – Fire and Explosion Hazard Data

Flash Point <i>(Method Used)</i> NON-FLAMMABLE	Flammable Limits N/A	LEL N/A	UEL N/A
Extinguishing Media WILL NOT BURN			
Special Fire Fighting Procedures NONE			
Unusual Fire and Explosion Hazards NONE			

Section V – Reactivity Data

Stability	Unstable	<input type="checkbox"/>	Conditions to Avoid
	Stable	<input checked="" type="checkbox"/>	NONE

Incompatibility (*Materials to Avoid*)

NONE

Hazardous Decomposition or Byproducts

NONE

Hazardous Polymerization	May Occur	<input type="checkbox"/>	Conditions to Avoid
	Will Not Occur	<input checked="" type="checkbox"/>	NONE

Section VI – Health Hazard Data

Route(s) of Entry	Inhalation? YES	Skin? YES	Ingestion? YES
-------------------	--------------------	--------------	-------------------

Health Hazards (*Acute and Chronic*)

EXCESSIVE OR LONG-TERM INHALATION MAY CAUSE IRRITATION TO NOSE, THROAT AND RESPIRATORY PASSAGES.

Carcinogenicity:	NTP? NO	IARC Monographs? NO	OSHA Regulated? NO
------------------	------------	------------------------	-----------------------

Signs and Symptoms of Exposure

EXPOSURE TO SKIN OR EYES MAY CAUSE RASH OR IRRITATION. INHALATION MAY CAUSE COUGH, SHORTNESS OF BREATH, WHEEZING AND REDUCED PULMONARY FUNCTION.

Medical Conditions Generally Aggravated by Exposure

ALLERGIES TO PORTLAND CEMENT, OR INDIVIDUALS WITH RESPIRATORY DISEASE OR SUBJECT TO EYE IRRITATION.

Emergency First Aid Procedures: SEEK MEDICAL ATTENTION. INHALATION MAY RESULT IN RESPIRATORY IRRITATION - REMOVE TO FRESH AIR. SKIN WASH WITH SOAP AND WATER. EYES - FLUSH WITH WATER. INGESTION - DILUTE WITH WATER.

Section VII – Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled

COLLECT USING DUSTLESS METHOD (HEPA VACUUM OR WET METHOD). WHERE APPROPRIATE – PROTECTIVE EQUIPMENT – COLLECT FOR DISPOSAL.

Waste Disposal Method

DISPOSE OF IN ACCORDANCE WITH ALL APPLICABLE LOCAL, STATE/PROVINCIAL AND FEDERAL REGULATIONS.

Precautions to Be Taken in Handling and Storing

NONE. STORE IN A COOL, DRY AREA. USE NORMAL PRECAUTIONS AGAINST BAG BREAKAGE. USE GOOD HOUSEKEEPING TO PREVENT DUST ACCUMULATION.

Other Precautions

DO NOT BREATHE DUST.

Section VIII – Control Measures

Respiratory Protection (*Specify Type*)

WEAR A NIOSH/MSHA APPROVED RESPIRATOR.

Ventilation	Local Exhaust To CONTROL TO RECOMMENDED P.E.L.	Special N/A
	Mechanical (<i>General</i>) N/A	Other N/A

Protective Gloves RECOMMENDED	Eye Protection RECOMMENDED
----------------------------------	-------------------------------

Other Protective Clothing or Equipment

AS APPROPRIATE FOR WORK ENVIRONMENT. COVERALLS, APRON AND BOOTS TO PREVENT CONTACT.

Work/Hygienic Practices

DUSTY CLOTHING SHOULD BE LAUNDERED BEFORE REUSE. WHEN FINISHED SHOWER WITH SOAP AND WATER TO REMOVE DUST.



Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration
(Non-Mandatory Form)

IDENTITY *(As Used on Label and List)*
ARDEX SD-F FEATHER FINISH – GRAY

Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.

Section I

Manufacturer's Name
ARDEX INC.

Emergency Telephone Number
(724) 857-6400

Address *(Number, Street, City, State and Zip Code)*

Telephone Number for Information
(724) 857-6400

400 Ardex Park Drive
Aliquippa, PA 15001
U.S.A.

Date Prepared
1/8/2001

Signature of Preparer *(Optional)*

Section II – Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity: Common Name(s))	OSHA PEL	ACGIH TLV	Other Limits Recommended	% <i>(optional)</i>
40% MAX PORTLAND CEMENT	65997-15-1	10MG/M ³	10MG/M ³	
45% MAX LIMESTONE	1317-65-3	N/A	30 MPPCF	
20% MAX VINYL ACETATE COPOLYMER	24937-78-8	10MG/M ³	10 MG/M ³	

Section III – Physical/Chemical Characteristics

Boiling Point	N/A	Specific Gravity (H ₂ O = 1)	1.2
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A

Solubility in Water

Less than 50 g/1000 cm³

Appearance and Odor

FINE GRAY POWDER - ODORLESS

Section IV – Fire and Explosion Hazard Data

Flash Point (Method Used) NON-FLAMMABLE	Flammable Limits N/A	LEL N/A	UEL N/A
Extinguishing Media WILL NOT BURN			
Special Fire Fighting Procedures NONE			
Unusual Fire and Explosion Hazards NONE			

Section V – Reactivity Data

Stability	Unstable	<input type="checkbox"/>	Conditions to Avoid
	Stable	<input checked="" type="checkbox"/>	NONE

Incompatibility (*Materials to Avoid*)

NONE

Hazardous Decomposition or Byproducts

NONE

Hazardous Polymerization	May Occur	<input type="checkbox"/>	Conditions to Avoid
	Will Not Occur	<input checked="" type="checkbox"/>	NONE

Section VI – Health Hazard Data

Route(s) of Entry	Inhalation? YES	Skin? YES	Ingestion? YES
-------------------	--------------------	--------------	-------------------

Health Hazards (*Acute and Chronic*)

EXCESSIVE OR LONG-TERM INHALATION MAY CAUSE IRRITATION TO NOSE, THROAT AND RESPIRATORY PASSAGES.

Carcinogenicity:	NTP? NO	IARC Monographs? NO	OSHA Regulated? NO
------------------	------------	------------------------	-----------------------

Signs and Symptoms of Exposure

EXPOSURE TO SKIN OR EYES MAY CAUSE RASH OR IRRITATION. INHALATION MAY CAUSE COUGH, SHORTNESS OF BREATH, WHEEZING AND REDUCED PULMONARY FUNCTION.

Medical Conditions Generally Aggravated by Exposure

ALLERGIES TO PORTLAND CEMENT OR INDIVIDUALS WITH RESPIRATORY DISEASE OR SUBJECT TO EYE IRRITATION.

Emergency First Aid Procedures: SEEK MEDICAL ATTENTION. INHALATION MAY RESULT IN RESPIRATORY IRRITATION - REMOVE TO FRESH AIR. SKIN WASH WITH SOAP AND WATER. EYES - FLUSH WITH WATER. INGESTION - DILUTE WITH WATER.

Section VII – Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled

COLLECT USING DUSTLESS METHOD (HEPA VACUUM OR WET METHOD). WHERE APPROPRIATE – PROTECTIVE EQUIPMENT – COLLECT FOR DISPOSAL.

Waste Disposal Method

DISPOSE OF IN ACCORDANCE WITH ALL APPLICABLE LOCAL, STATE/PROVINCIAL AND FEDERAL REGULATIONS.

Precautions to Be Taken in Handling and Storing

NONE. STORE IN A COOL, DRY AREA. USE NORMAL PRECAUTIONS AGAINST BAG BREAKAGE. USE GOOD HOUSEKEEPING TO PREVENT DUST ACCUMULATION.

Other Precautions

DO NOT BREATHE DUST.

Section VIII – Control MeasuresRespiratory Protection (*Specify Type*)

WEAR A NIOSH/MSHA APPROVED RESPIRATOR.

Ventilation	Local Exhaust TO CONTROL TO RECOMMENDED P.E.L.	Special N/A
	Mechanical (<i>General</i>) N/A	Other N/A

Protective Gloves RECOMMENDED	Eye Protection RECOMMENDED
----------------------------------	-------------------------------

Other Protective Clothing or Equipment

AS APPROPRIATE FOR WORK ENVIRONMENT. COVERALLS, APRON AND BOOTS TO PREVENT CONTACT.

Work/Hygienic Practices

DUSTY CLOTHING SHOULD BE LAUNDERED BEFORE REUSE. WHEN FINISHED SHOWER WITH SOAP AND WATER TO REMOVE DUST.